
- hypothesis experiment evaluation
- plan do check
- specification production inspection
- define measure analyze improve control






W. Edwards Deming

Walter A. Shewhart

### Shewart-Deming Cycle




PLAN: Design or revise business process components to improve results

DO: Implement the plan and measure its performance


CHECK/STUDY: Assess the measurements and report the results to decision makers

**ACT**: Decide on changes needed to improve the process



Click to LOOK INSIDE!

## W. Edwards Deming




# THE NEW ECONOMICS

FOR INDUSTRY GOVERNMENT EDUCATION

Second Edition

### Inicializácia



#### TQM vs. Traditional Organization

- Customer driven
- Long-term oriented
- Data driven
- Elimination of waste
- Continuous improvement
- Prevention
- Employee participation
- Problem solving
- Leadership

Company driven

Short-term oriented

Opinion driven

Tolerance of waste

**Optimization** 

Inspection

Top-down hierarchy

Blame imposing

Management

